















147 POINT VEHICLE INSPECTION



INSPECTION AREA	RESULT
 MECHANICAL COMPONENTS	 PASS
 VEHICLE OPERATION & CONTROLS	 PASS
 SAFETY SYSTEMS	 PASS
 LIGHTING SYSTEMS	 PASS
 TYRES & BRAKES	 PASS
 ENGINE BAY INSPECTION	 PASS
 ROAD TEST ASSESSMENT	 PASS

Inspection outcomes are based on a visual and operational assessment of the vehicle's condition and roadworthiness at the time of evaluation. Checks are completed where relevant to the individual vehicle specification.

147 POINT INSPECTION

STATUS PASS FAIL

This vehicle has successfully **passed** our 147 Point Mechanical & Operational Inspection and has been prepared to JW Autos standards.

Lighting

- ✓ Side lights
- ✓ Headlights
- ✓ Main beam
- ✓ Brake lights
- ✓ Number plate lights
- ✓ Rear lights
- ✓ Reverse lights
- ✓ Fog lights
- ✓ Hazard lights

Engine & Fluids

- ✓ Brake fluid level
- ✓ Screen wash topped up
- ✓ Power steering level
- ✓ Auxiliary belt
- ✓ Coolant hoses
- ✓ Radiator
- ✓ Fuel lines
- ✓ A/C condenser
- ✓ A/C compressor
- ✓ Ancillary components

Interior Functions

- ✓ Seat adjustment
- ✓ Seat belt operation
- ✓ Sun visor/sunroof
- ✓ Seat condition
- ✓ Heated seats
- ✓ Window operation
- ✓ Wipers
- ✓ Horn
- ✓ Fuel gauge
- ✓ Temperature gauge
- ✓ Warning lights
- ✓ Audio system
- ✓ Front camera
- ✓ Rear camera
- ✓ Parking aid
- ✓ Clock checked
- ✓ Power outlets
- ✓ Door mirrors
- ✓ Mirrors
- ✓ Central locking
- ✓ A/C

Exterior Functions

- ✓ Wiper blades
- ✓ Bonnet lock
- ✓ All doors lock
- ✓ Aerial

Road Test

- ✓ Braking
- ✓ Parking brake
- ✓ Steering
- ✓ Cruise control
- ✓ Clutch
- ✓ Gear change
- ✓ Heaters

Brakes

- ✓ Front brake pads
- ✓ Rear brake pads
- ✓ Disc condition (front and rear both checked)

Tyres

- ✓ Tyre tread checked